

Because it's easier!

Airfit




Urinal intake fittings for UP 1/2" with seal

The problem:


The connection size between the intake and the outflow doesn't match.

The solution:

Airfit offset intake fittings.




Urinal intake fittings for UP 1/2" with seal
5 mm offset!




Item no. 90002UZ

Urinal intake fittings for UP 1/2" with seal
10 mm offset!



Item no. 90003UZ

Urinal intake fittings for UP 1/2" with seal
No offset!



Item no. 90001UZ



Seal for urinal intake

Item no. 90004UZ